Docket No.: MP1483
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:
Daniel Yellin

Patent No.: 7,428,260

Issued: September 23, 2008

For: UNIFIED MMSE EQUALIZATION AND
      MULTI-USER DETECTION APPROACH FOR
      USE IN A CDMA SYSTEM

REQUEST FOR CERTIFICATE OF CORRECTION
PURSUANT TO 37 CFR 1.323

Attention: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted typographical errors which should be corrected.

In the Application		In the Patent		Error
In the Drawings:				
Sheet	**Figure**	**Sheet**	**Figure**	
Replacement Drawings August 9, 2007 Sheet 2	2	2	2	PTO
In the Specification:				
Page	**Line(s)**	**Column**	**Line(s)**	
8	15	4	57	PTO

8	21	4	64	PTO
8	26	5	5	PTO
8	27	5	6	PTO
8	29	5	9	PTO
9	7	5	20	PTO
14	23	8	40	Applicant
15	17	8	65	PTO
18	15	11	5	PTO
18	24	11	15	PTO
21	13	13	10	PTO
21	14	13	11	PTO
21	15	13	15	PTO
22	3	13	34	PTO
22	7	13	40	PTO
24	27-28	15	17-18	PTO

In the Claims:

Amendment	Claim	Line	Column	Line	
August 9, 2007 Page 9	32	9	19	21	Applicant

Two of the errors were found in the application or an amendment as filed by Applicant. Our check in the amount of $100.00 covering the fee set forth in 37 CFR 1.20(a) is enclosed.

With regard to Sheet 2, Fig. 2 in the drawings, it appears that the Office published the annotated sheet instead of the replacement sheet submitted with the Amendment dated August 9, 2007.

The errors now sought to be corrected are inadvertent typographical errors the correction of which does not involve new matter or require reexamination.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

The Director is hereby authorized to charge any deficiency in the fees filed, asserted to be filed or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our Deposit Account No. 13-2855, under Order No. 31146/MP1483.

Dated: December 1, 2008   Respectfully submitted,

By
Gregory E. Stanton
   Registration No.: 45,127
MARSHALL, GERSTEIN & BORUN LLP
233 S. Wacker Drive, Suite 6300
Sears Tower
Chicago, Illinois 60606-6357
(312) 474-6300
Attorney for Applicant

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page __1__ of __3__

PATENT NO.   :   7,428,260

APPLICATION NO.   :   10/697,853

ISSUE DATE   :   September 23, 2008

INVENTOR(S)   :   Daniel Yellin

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Specification:

At Column 4, line 57, "$g_1(t)$" should be -- $g_i(t)$ --.

At Column 4, line 64, "$g_1(t)$" should be -- $g_i(t)$ --.

At Column 5, line 5, "$g_1(t)$" should be -- $g_i(t)$ --.

At Column 5, line 6, "$g_1(t)$" should be -- $g_i(t)$ --.

At Column 5, line 9, "Further-more" should be -- Furthermore --.

At Column 5, line 20, "$\forall k_1 k_2$" should be -- $\forall k_1 \neq k_2$ --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):
Gregory E. Stanton
MARSHALL, GERSTEIN & BORUN LLP   1
233 S. Wacker Drive, Suite 6300
Sears Tower
Chicago, Illinois 60606-6357

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

At Column 8, line 40, "in-fact" should be -- in fact --.

At Column 8, line 65, "MM" should be -- MAI --.

At Column 11, line 5, "$g_1(t)$" should be -- $g_i(t)$ --.

At Column 11, line 15, "$g_1(t)$" should be -- $g_i(t)$ --.

At Column 13, line 10, "$h_1(t)$" should be -- $h_i(t)$ --.

At Column 13, line 11, "$h_1(t)$" should be -- $h_i(t)$ --.

At Column 13, line 15, "$h_1(t)$" should be -- $h_i(t)$ --.

At Column 13, line 34, "$h_1(t)$" should be -- $h_i(t)$ --.

At Column 13, line 40, "$g_1(t)$" should be -- $g_i(t)$ --.

At Column 15, lines 17-18, "chip-rate 1=1 equalizer" should be -- chip-rate equalizer --.

In the Claims:

At Column 19, line 21, "MUD_type" should be -- MUD-type --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):
Gregory E. Stanton
MARSHALL, GERSTEIN & BORUN LLP   2
233 S. Wacker Drive, Suite 6300
Sears Tower
Chicago, Illinois 60606-6357

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Page __3__ of __3__

<u>In the Drawings:</u>
At Sheet 2, figure 2, the drawing should be:

$$\hat{a} = \sum_{m_1}^{m_2} w_k^* \cdot y_k$$

Fig. 2

MAILING ADDRESS OF SENDER (Please do not use customer number below):
Gregory E. Stanton
MARSHALL, GERSTEIN & BORUN LLP   3
233 S. Wacker Drive, Suite 6300
Sears Tower
Chicago, Illinois 60606-6357